

FIG. 1




FIG. 2




FIG. 3

	<u>NEXT</u>
	STATE S
	0001
	0010
	0011
	0100
	0101
I OW RITS	0110
= 111	0111
	1000
XOR WITH	1001
HIGH BIT	1010
	1011
	1100
	1101
I OW RITS	1110
= 111	1111
7	0000
XOR WITH HIGH BIT	
	XOR WITH HIGH BIT  LOW BITS = 111  XOR WITH

FIG. 4

